



COMPONENTS ORIENTED AS IN DRIVER'S FOOTWELL SOBill@aol.com 10 OCT. '02 *** REVISED 5 NOV. 02**

RELAYS AND WARNING BUZZERS WIRING (LATE)